M.A. R. 57 (Rule 116)
Measurement Book

No. B 179310

AEE/SSD/SSK 5/11/16-17 A-29-6-16

Repair & Part.

Name of Maintainance of borewell at Shettyhalli Abbigere, Medarahalli & chikkasandra From ..... To .....

Ward No-12 S.S.D.

Contractor of nature of Agency..... S. Prakash. Jci- 012-16-000010

Commencement of work..... NO EE/DD/WO/06/16-17 Dt-27/4/16. Est cost :- 35.0 lakhs.

Full description, etc, of work	Number	Dimensions Length	Breadth	Depth	Contents	Reference to last Measurement
2	3	4	5	6	7	8
Repair to Motor; Rewinding of Submersible Pumpsets with copper insulation wire of suitable gugge as per IS) Qualification gurantee of 6months For 7.5HP complete as per Specifications.						
Medarahalli Near Madurarmma temple.	1 NO				= 1.0 NO	
Shettyhalli Byraveshwara Nagara 4th cross	1 NO				= 1.0 NO	
Pampegowda garden near Lokesh House.	1 NO				= 1.0 NO	
Medarahalli gode Palya. near Tulasi house	1 NO				= 1.0 NO	

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurem
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Cl&a Re						
	Add GI pipe theading & transportation charge @ Rs 27 Per Mtf 6.0mtr x 27 complete as per specification						
			1x155			= 155.00 Mt @ 162=00 Rs	25110=00
	certified that contractor has done the work satisfactory.					Total Amount: 2789820=00	
	certified that contractor has removed all debris from work spot.					27833620	
	certified that there is no due work from contractor side.						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಲೆಕ್ಕಶೀರ್ಷಿಕೆ ಉಪವಿಭಾಗ, ಬಾಗೇಪಲ್ಲಿ
ಬೃಹತ್ ಬೆಂಗಳೂರು ನೀರು ಸರಬರಾಜು
ಮತ್ತು ಎಂ. ಆರ್. ಡಬ್ಲ್ಯೂ. ಎಸ್. ಯೋಜನೆ

M. A. R. 57 (Rule 116)
Measurement Book

No. B 179331

..... From ..... To .....

Description of nature of Agency .....

Description of work .....

Description of work	Number	Dimensions: Length	Dimensions: Breadth	Dimensions: Depth	Contents	Reference to last Measurement
	3	4	5	6	7	8

Executive Engineer